



rapitest®

Products for
Successful Gardening **Digital Soil Thermometer**

INSTRUCTIONS:

Press the power button to turn the thermometer on and off. With the unit turned on, insert the thermometer to a minimum depth of 2" to 3" (5-8 cm) into the soil. Check the temperature recorded after about 60 seconds.

If not turned off, the unit will turn itself off after about 3 minutes to preserve battery life. Press the power button to re-start.

Replacement batteries:

Three (3) #357 silver oxide, 1.55 volt

Soil Temperature Ranges

VEGETABLE	WILL GERMINATE	IDEAL GERMINATION	TRANSPLANTING SEEDLINGS OUT
ASPARAGUS	50F-90F	70F	
BEANS	60F-90F	80F	
BEET	40F-90F	80F	
BROCCOLI	40F-90F	80F	50F
CABBAGE	40F-90F	80F	45F
CANTALOUPE	60F-100F	90F	65F
CARROT	40F-90F	80F	
CAULIFLOWER	40F-90F	80F	
CELERY	40F-80F	70F	45F
CHARD	40F-90F	80F	
CORN	50F-100F	80F	60F
CUCUMBER	60F-100F	90F	65F
ENDIVE	40F-75F	75F	
LETTUCE	40F-75F	75F	
OKRA	60F-100F	90F	70F
ONION	40F-100F	90F	45F
PARSLEY	40F-90F	80F	
PARSNIP	40F-90F	70F	
PEAS	40F-80F	70F	45F
PEPPER	60F-90F	80F	65F
PUMPKIN	60F-100F	90F	65F
RADISH	40F-90F	80F	
SPINACH	40F-80F	75F	
SQUASH	60F-100F	90F	65F
TOMATO	50F-100F	80F	60F
WATERMELON	60F-110F	90F	65F

Luster Leaf Products, Inc.

2220 Techcourt

Woodstock, Illinois 60098

Designed and engineered in the USA,
Made in China

